


## COMPONENT VIEW



## **FITTINGS**

| Α |  | 10x40     | x37 |
|---|--|-----------|-----|
| В | 9————————————————————————————————————— | 6,3x105   | x8  |
| С | (a)                                    | M6x100    | x10 |
| D | 8                                      | M6x10x13  | x11 |
| Е |  | 7×50      | ×20 |
| F | 9www                                   | 55/12,2x5 | x8  |
| G | Œ                                      | D8x13     | x10 |

| Н | T          | D10x15     | x5  |
|---|------------|------------|-----|
| J | (8)        | 5x30       | хЗ  |
| K | (a)        | M6x120     | x1  |
| L | (a)        | M6x80      | x1  |
| М | <b>0</b> D | M6x8x12x15 | x1  |
| N | <b>(b)</b> | 3,5x40     | x27 |
| Р |            | 4mm        | x2  |